

Engineering Release Notes

Cobalt Digital Inc. ● 2506 Galen Drive ● Champaign IL 61821 USA ● (217) 344-1243 ● www.cobaltdigital.com ● support@cobaltdigital.com

This release is intended for the ROYAL 9917-DA-1x8/2x4-12G Dual-Channel 12G/6G/3G/HD/SD Reclocking Distribution Amplifier.

You can update your firmware by going to the **Support>Firmware** link at <u>www.cobaltdigital.com</u> (<u>Firmware | Audio/Video Production Products | Cobalt Digital</u>).

Refer to the **Firmware Update Instructions**, which provides instructions for downloading the latest firmware for your control panel onto your computer, and then uploading it to your controller through DashBoard™.

The following table lists released software versions and describes the corresponding functions additions, improvements and/or corrections.

Firmware Version	Description
ROYAL 9917-DA Release v1.1.4	Added Features
	 Product name change. New product name is ROYAL 9917-DA -1x8/2x4- 12G. Previous name was ROYAL OG-DA -1x8/2x4-12G.
ROYAL OG-DA Release v1.1.3	Resolved Issues
	 Resolved a DIP switch issue that
	caused DashBoard status to not
	reflect the correct switch setting.
	DashBoard alarm parameters are no
	longer immutable in remote mode.