Cobalt Digital Inc. • 2506 Galen Drive • Champaign, IL 61821 USA • 1-217-344-1243 • www.cobaltdigital.com • support@cobaltdigital.com

You can update your card by downloading the new Update software by going to the **Support>Firmware** link at www.cobaltdigital.com. Download "Firmware Update Guide", which provides simple instructions for downloading the latest firmware for your card onto your computer, and then uploading it to your card through DashBoard™.

Software updates are field-installed without any need to remove the card from its frame.

The table below lists released software versions and describes the corresponding functions additions, improvements and/or corrections.

Software Version (Date)	Description
1.2.11 (1/27/2021 – present) 9410DA-(EO; 2EO; OE; 2OE; EOOE) 9415DA-SFP	**Corrections:** • Modify UI to use nomenclature for coax outputs that matches that used on Rear I/O Module labelling. **Note:** If this UI revision is not needed or considered necessary in your usage, this release does not need to be uploaded to card(s). Card functionality/performance has not been changed.
1.2.8 (8/25/2020 – 1/27/2021) 9410DA-(EO; 2EO; OE; 2OE; EOOE) 9415DA-SFP	**Improvements:** • Previous versions showed fiber input status only from info derived from reclocker function. As such, a valid MADI fiber input (which is not reclocked or recognized by the recloker) would not indicate signal presence. This version uses level presense (energy) for non-reclockable inputs (such as MADI) and shows recloker-derived status for SMPTE video SDI signals. MADI and similar signal show "Signal Present" for valid input, and SMPTE SDI signals show (for example) "HD Signal Present".
1.2.6 (9/10/2019 – 8/25/2020) 9410DA-(EO; 2EO; OE; 2OE; EOOE) 9415DA-SFP	**Additions:** • Adds support for rear module MPN 1948.
1.1.19 (2/16/2018 – 9/10/2019) 9410DA-(EO; 2EO; OE; 2OE; EOOE) 9415DA-SFP	• Manufacturing maintenance release; no action needed.
1.1.1 (9/11/2017 – 2/16/2018) 9410DA-(EO; 2EO; OE; 2OE; EOOE) 9415DA-SFP	**Additions:** • Adds SNMP support.
1.0.12 (12/1/2016 – 9/11/2017) 9410DA-(EO; 2EO; OE; 2OE; EOOE) 9415DA-SFP	• Initial production release.