

Cobalt Digital Inc. • 2506 Galen Drive • Champaign IL 61821 USA • (217) 344-1243 • www.cobaltdigital.com • support@cobaltdigital.com

This release is intended for the following ARIA products:

- ARIA OG-AUD2-DANTE
- ARIA OG-AUD4-DANTE

You can update your firmware by going to the **Support>Firmware** link at <u>www.cobaltdigital.com</u> (Firmware | Audio/Video Production Products | Cobalt Digital).

Refer to the **Firmware Update Instructions**, which provides instructions for downloading the latest firmware for your control panel onto your computer and then uploading it to your controller through DashBoard[™].

The following table lists released software versions and describes the corresponding functions additions, improvements and/or corrections.

Firmware Version	Description
ARIA OG-AUD2/AUD4-DANTE Release v1.0.2	Bux Fixes Corrected an issue where a user could inadvertently route AES inputs to other audio outputs.
	When bi-directional AES audio groups are switched from input to output, the device now updates the audio bus route selections to remove the AES inputs preventing users from accidentally routing them.
ARIA OG-AUD2/AUD4-DANTE Release v1.0.1	Bux Fixes Corrected an issue that prevented users from routing MADI/Dante audio signals to the downmixer and/or the flexmixer.